



PT100-1

Screw-in type PT100




This is a most commonly used screw-in type PT100, standard version with M6 screw and 2 meters stainless steel cable

PT100-1-N-N-M6-2000-SS-200
 Type: PT100-1
 screw in type
 2 meters lead wire
 M6*0.75mm screw
 Range: 200 C degree

PT100-2

Probe type PT100 with process fittings




This is a most commonly used probe PT100, standard version with M8 screw and 2 meters cable, standard model with range up to 300°C

PT100-2-5-100-M8-2000-SS-200
 Type: PT100-2, probe type
 Probe diameter and length: 5mm*100mm
 M8*1mm screw
 2 meters cable
 Range: 200 C degree

PT100-3

RTD with connection box and process fittings

Form B connection box



This is a popular PT100 with connection box, for harsh environments with process fittings, like 1/2 NPT etc

PT100-3-5-100-1/2NPT-N-CB-300
 Type: PT100-3
 Probe diameter and length: 5mm*100mm
 Process fittings: 1/2NPT
 No lead wire
 Form B connection box
 Range: maximum 300 C degree